



FIG. 1








FIG. 4






FIG. 5






**Title: Electrical Service Disconnect Having Tamper Detection
Inventor: Holle et al.
App. No. 10/085,426
Page 6 of 7
Replacement Sheet**



223 FIG. 7



88